

Island County Water Well Information



WellKey: 9XC

General Information

Owner Name (log): R. D. King

DOE Tag: AKY790

DOE NOI: [10716](#)

DOE ID

[83095](#)

Well Address: NE 1/4 SW 1/4

Well Parcel: [S6125-00-00002-2](#)

Served Parcel:

Horiz/Vert Accuracy: Site Plan / DEM

Site Type: Well within

SWI Rating: No Data



Construction Information

Construction Date: Sep 1972

Driller Name: Owner


LS Elevation: 14 ft. MSL

Depth Well: 185 ft.

TD Elevation: -171 ft. MSL

WL Measurements: [1 measurement \(Click to View\)](#)

WL Elevation: -57 ft. MSL



Water Quality Information

Water Samples: [4 samples \(Click to View\)](#)

Avg/Med/Max Arsenic:

Avg/Med/Max Chloride:

Avg/Med/Max Hardness:

Avg/Med/Max Nitrate: 1.18 / 0.25 / 4.1 mg/l

Bacteria Samps (distribution): [13 samples \(Click to View\)](#)

Public Water System Information

Pws Name: Ben Ure Island Community

PwsID: [02433](#)

Water System Active Sources (SO# / SO Name)

[01 / WELL 1](#)

[02 / Well 2 AKY790](#)

Approved Connects: 0

Pws Source #: SO# 1

Pws Source Name: WELL #1

Depth/
Elev(ft)

0/14

-25/-11

-50/-36

-75/-61

-100/-86

-125/-111

-150/-136

-175/-161

185/-171

Note: Underlined items in **bright blue** are hyperlinks to additional information / resources.
Questions? Contact the [Island County Hydrogeologist](#), or visit the [Hydrogeology Web Page](#).

Report Generated: 12/20/2020